

TABLA PRESIÓN TEMPERATURA CO2 - 744

T	P
° C	Bar
-56,6	5,2
-56	5,312
-55	5,546
-54	5,788
-53	6,038
-52	6,296
-51	6,562
-50	6,836
-49	7,119
-48	7,41
-47	7,71
-46	8,018
-45	8,336
-44	8,663
-43	9
-42	9,346
-41	9,701
-40	10,067
-39	10,442
-38	10,828
-37	11,224
-36	11,631
-35	12,048
-34	12,477
-33	12,916
-32	13,367
-31	13,829
-30	14,303
-29	14,788
-28	15,286
-27	15,796
-26	16,318
-25	16,852
-24	17,4
-23	17,96
-22	18,533
-21	19,12
-20	19,72
-19	20,334
-18	20,961
-17	21,603
-16	22,259
-15	22,929
-14	23,614
-13	24,313
-12	25,028
-11	25,758
-10	26,504
-9	27,265
-8	28,042

PUNTO TRIPLE

T	P
° C	Bar
-7	28,835
-6	29,644
-5	30,47
-4	31,313
-3	32,173
-2	33,05
-1	33,944
0	34,857
1	35,787
2	36,735
3	37,702
4	38,688
5	39,693
6	40,716
7	41,76
8	42,823
9	43,906
10	45,01
11	46,134
12	47,279
13	48,446
14	49,634
15	50,844
16	52,077
17	53,332
18	54,611
19	55,914
20	57,242
21	58,594
22	59,973
23	61,378
24	62,812
25	64,274
26	65,766
27	67,289
28	68,846
29	70,437
30	72,065
31	73,733
31,06	73,834

PUNTO TRANSCRITICO

TODAS LAS PRESIONES SON ABSOLUTAS
 PRESION MANOMETRICA = PRESION ABSOLUTA - 1 BAR (aprox.)